










# Salford, Greater Manchester



Project description	Whole house retrofit of mid-terrace house, built c.1900.																		
Treated Floor Area	70 m <sup>2</sup>																		
Dates of work	2008 – 2010																		
Project team	Myself, along with various sub-contractors for different tasks																		
Introduction	House was damp and dark when I bought it, and parts of the house (e.g. the bathroom) were freezing in cold weather. I had to do a certain amount of things anyway since the house was in a fairly bad state (e.g. window frames were rotten), so I found that this was a good time to try to make it better while I was at it. I didn't know much about energy efficiency or in what order to do things, so I spent some cash on a few books and read up about what I should do, after which I made a do-list and decided roughly in what order things should be done.																		
Space heating demand & carbon emissions – before and after according to PHPP	<div style="display: flex; justify-content: space-around;"> <div style="width: 45%;"> <p><b>Before:</b></p> <p><b>After:</b></p> </div> <div style="width: 45%;"> <table border="1"> <thead> <tr> <th></th> <th>Before</th> <th>After</th> <th>% reduction</th> </tr> </thead> <tbody> <tr> <td>Space heating (kWh/m<sup>2</sup>/yr)</td> <td>248.8</td> <td>78</td> <td>69%</td> </tr> <tr> <td>Primary energy (kWh/m<sup>2</sup>/yr)</td> <td>467.3</td> <td>179.8</td> <td>62%</td> </tr> <tr> <td>CO2 (kg/m<sup>2</sup>/yr)</td> <td>107.7</td> <td>42.9</td> <td>60%</td> </tr> </tbody> </table> </div> </div>				Before	After	% reduction	Space heating (kWh/m <sup>2</sup> /yr)	248.8	78	69%	Primary energy (kWh/m <sup>2</sup> /yr)	467.3	179.8	62%	CO2 (kg/m <sup>2</sup> /yr)	107.7	42.9	60%
	Before	After	% reduction																
Space heating (kWh/m <sup>2</sup> /yr)	248.8	78	69%																
Primary energy (kWh/m <sup>2</sup> /yr)	467.3	179.8	62%																
CO2 (kg/m <sup>2</sup> /yr)	107.7	42.9	60%																
Fuel use before and after	No data before, as I had just moved in. Data after retrofit does not give accurate picture due to many periods when house has been unoccupied, especially during cold months.																		
What improvements done / strategies	<b>Improvement</b>		<b>U-values / information</b>																
	Insulation Bathroom ceiling		- Polyisocyanurate (Kingspan) 120mm thick friction-fitted in rafters, u-value 0.321 W/m <sup>2</sup> K																

		
	<p>Internal walls (external-facing – i.e. not party walls)</p>	<ul style="list-style-type: none"> <li>- Polyisocyanurate (Kingspan) 70mm thick friction-fitted in studwork, u-value 0.372 W/m<sup>2</sup>K</li> </ul> 
	<p>Suspended timber floor</p>	<ul style="list-style-type: none"> <li>- Polyisocyanurate (Kingspan) 100mm thick friction-fitted between joists, u-value 0.321 W/m<sup>2</sup>K</li> </ul> 
	<p>Loft</p>	<ul style="list-style-type: none"> <li>- Mineral wool 270mm thick, u-value 0.149 W/m<sup>2</sup>K</li> </ul>
	<p>Bay window ceiling above French doors</p>	<ul style="list-style-type: none"> <li>- Polyisocyanurate (Kingspan) 100mm thick friction-fitted between rafters, u-value 0.332 W/m<sup>2</sup>K</li> </ul>

		
<b>Airtightness</b>		
	<p>Some vapour-impermeable sheeting, combined with use of expanding foam</p>	<ul style="list-style-type: none"> <li>- Vapour-impermeable polythene sheets used on insulated internal walls and bathroom ceiling, but these were not adequately taped or sealed to create a draught proof barrier</li> <li>- No membrane was used on ground floor – here I only relied on expanding foam</li> <li>- No membrane used on bedroom ceilings – here I used expanding foam to seal up between plasterboards and wire penetrations via the loft space</li> </ul> 
<b>Ventilation</b>		
	<p>Mechanical Ventilation with Heat Recovery (MVHR) unit installed</p>	<ul style="list-style-type: none"> <li>- Xpelair Xcell-300 unit installed in loft, 91% heat recovery</li> <li>- Air is extracted from kitchen &amp; bathroom and supplied to 2 bedrooms and lounge via 125mm round/rectangular ductwork and 180mm insulated ductwork in the loft space</li> </ul>

		<ul style="list-style-type: none"> <li>- 82 m<sup>3</sup>/hour measured flow rate, which is the lowest flow rate possible before fans cut out – which means ventilation rate of 0.45 air changes per hour</li> <li>- Humidity in house varies within the 40-60% range, but occasionally dips below 40% in winter.</li> </ul>
		
	Doors & windows	
	New windows and doors	<ul style="list-style-type: none"> <li>- Rehau PVC double-glazed windows and French doors, with 28mm gap argon-filled glazing, u-value of whole window 2.2 W/m<sup>2</sup>K (glazing u-value 1.5 W/m<sup>2</sup>K)</li> <li>- One Velux wood-framed window in bathroom, u-value of whole window 1.98 W/m<sup>2</sup>K (glazing u-value 1.1 W/m<sup>2</sup>K)</li> </ul>
		
Damp		
Ground floor & walls	- I had an injected damp course done on the whole ground floor	

		<ul style="list-style-type: none"> <li>- Kitchen floor had to be drilled up and re-laid (rising damp due to inadequate DPM)</li> </ul> 
	Crawl space	<ul style="list-style-type: none"> <li>- Put 4.5 tonnes of MOT (gravel mix) onto the muddy crawl space floor to soak up moisture and deal with mud and unevenness</li> <li>- After that I laid a thick polythene sheeting on top of this to reduce evaporation (cleared up the condensation on windows overnight)</li> </ul> 
	<b>Heating system</b>	
	Condensing boiler	<ul style="list-style-type: none"> <li>- Replaced old boiler with Remeha Avanta Plus condensing boiler</li> </ul>
Radiators	<ul style="list-style-type: none"> <li>- New radiators throughout, most with TRVs</li> </ul>	
Wood-burning stove	<ul style="list-style-type: none"> <li>- Løvenholm 5kW HETAS-approved smokeless zone stove put into larger chimney breast on ground floor</li> <li>- Appropriate chimney cowl added to stack</li> </ul>	

		
	Appliances & electrics	
	Appliances	- New energy-efficient washing machine, fridge, freezer
	Lighting	- Low energy CFLs and LEDs in most fittings
	Water	
Sink, toilet & bath	- Ifö sink, toilet & bath which are designed to save water by design (e.g. toilet flush 2 or 4 litres)	
What would I have done differently?	- Better airtightness using vapour-permeable membranes on most surfaces, and non vapour-permeable membrane on ground floor: this was my first renovation, and following advice from a book, my airtightness strategy	

	<p>consisted largely of using expanding foam, which I now know is not an effective strategy. The polythene sheets were also not vapour permeable, and in any case were not correctly joined together or to walls/floors.</p> <ul style="list-style-type: none"> <li>- Proper MVHR design prior to procuring unit, to ensure that a lower flow rate can be achieved that would result in 0.3 air changes per hour in winter (to avoid dry air).</li> <li>- Wood fibre as insulation for internal wall insulation</li> <li>- Insulation for kitchen floor prior to concrete being laid</li> <li>- External wall faces treated with Keim Lotexan mineral paints (to reduce rain-driven moisture)</li> <li>- Better suspended floor insulation strategy – namely to put vapour-impermeable membrane beneath floor joists and sealed to crawl space walls, followed by vapour-impermeable insulation – e.g. polyisocyanurate. (This is following more than 12 months of research on joist moisture content that is still ongoing with the AECB and an academic researcher).</li> </ul>		
Fan test results		Air changes per hour	m <sup>3</sup> / hour / m <sup>2</sup>
	Test 1: before	Not carried out	Not carried out
	Test 2: after insulation	9.34	7.85
	Test 3: after plastering	Not carried out	Not carried out
Cost	<p>£40,000, of which:</p> <ul style="list-style-type: none"> <li>- 50% was related to energy efficiency work</li> <li>- 50% was spent on things like new kitchen &amp; bathroom, knocking walls through, carpets, paint, furniture, etc.</li> </ul>		